View of the north wall and second floor joists, during renovation of White House



Description
View of the north wall and second floor joists after the lath and plaster was removed from the ceiling of the Family Dining Room during the renovation of the White House. Clamps were installed to hold the cracked beam late in 1948.

Date(s)
March 7, 1950

Accession Number 71-217

8x10 inches (21x26 cm) Black & White

Related Collection Harry S. Truman Papers

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.