

# White House, Bathroom



## Description

Southwest view from Bathroom B-14, taken during the renovation of the White House. The brick wall, one of the main support columns of the White House, was weakened by cutting into the bricks for installation of a water pipe many years ago.

## Date(s)

February 23, 1950

**Accession Number** 58-531-022

8x10 inches (21x26 cm)      Black & White

**Keywords** Building repair and reconstruction      Dwellings      Presidential residences      Historic buildings  
Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.