## View of center archway, second floor corridor of the White House

Description

the carpenters.

February 8, 1950

Date(s)

View of center archway of north wall of second floor corridor of the White House, during the renovation. Some of the wooden trusses have been removed by



8x10 inches (21x26 cm) Black & White

**Keywords** Building repair and reconstruction
Historic buildings

Dwellings Presidential residences

Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

**Credit:** Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.