

# Lower corridor of the White House



## Description

View of the north wall of the lower corridor east of center of the White House. The doorway on the right, bricked up for many years, was revealed when the plaster was removed.

## Date(s)

February 2, 1950

**Accession Number** 58-531-041

8x10 inches (21x26 cm)      Black & White

**Keywords** Building repair and reconstruction      Dwellings      Presidential residences      Historic buildings  
Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.