

Southeast View of Yellow Bathroom in the White House



Description

Southeast view of the Yellow Bathroom (B-13), into corridor and brick wall west of the stairway, which is one of the main support columns of the building. The wall has been weakened greatly by cutting into the bricks for the installation of the water pipes shown in the photograph. From a series of photographs of the renovation of the White House.

Date(s)

February 23, 1950

Accession Number 58-531-100

8x10 inches (21x26 cm) Black & White

Keywords Building repair and reconstruction Dwellings Presidential residences

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.