

Storage building construction at the White House



Description

View during construction of large storage building south of the White House. The steps and foundation of the South Portico and stone floor of the Lobby are stacked at the side. This is from a series of photographs of the renovation of the White House.

Date(s)

January 17, 1950

Accession Number 58-531-084

8x10 inches (21x26 cm) Black & White

Keywords Building repair and reconstruction Dwellings Presidential residences

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.