View of north front of the White House during renovation



Description
View of north front of the White House. The Seneca stone wall east of the North Portico has been removed and excavation begun to remove water pipes preparatory to enlarging storage area under the lawn. The temporary cable carries electricity from one wing to the other.

Date(s)
March 3, 1950

Accession Number 71-207

8x10 inches (21x26 cm) Black & White

Related Collection Harry S. Truman Papers

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.