

North View From Blue Room of White House During Renovation



Description

North view from Blue Room of the White House during renovation, elevated to second and third floor corridors and skylight. The brick wall is being taken down from the third floor ceiling for installation of steel shoring columns. Two African American workmen stand on part of the brick wall.

Date(s)

March 13, 1950

Accession Number 71-224

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.