

Abbie Rowe photographs progress during renovation of White House



Description

National Park Service photographer Abbie Rowe photographs progress in completing underpinning east of South Portico during the White House renovation. When most of underpinning is completed, the stone foundation will be taken down, the opening used to remove earth from area inside.

Date(s)

March 21, 1950

Accession Number 71-236

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

People Pictured Rowe, Abbie, 1905-1967

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.