

View of west face and south portico of the White House during renovation



Description

View of west face and south portico of the White House during renovation, showing temporary wooden steps to the roof and the chute from the southwest window of the Monroe Room to hopper used for disposal of debris from 2nd and 3rd floors.

Date(s)

March 21, 1950

Accession Number 71-239

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.