


View along north face of the White House during renovation



Description

View along north face of the White House near the northwest corner. The concrete shoring columns on this face have been completed except for the small area shown in the photograph. The stone here will be removed and the opening used for removing earth during excavation below the basement. The pipe which carries surface water from the roof, was re-laid farther to the north to permit this operation.

Date(s)

April 10, 1950

Accession Number 71-257

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.