

Photograph under center pier in the Broadcasting Room during White House renovation



Description

Photograph under center pier in the Broadcasting Room, 4 feet below old foundation, during the renovation of the White House. The steel wedging beams were installed to test amount of weight on foundation. The jacks were raised so that building above moved 1 millimeter, instruments recorded a pressure of 76 tons.

Date(s)

May 2, 1950

Accession Number 71-287

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.