

View of North Hall of 3rd Floor Corridor during renovation of the White House



Description

View of North Hall of 3rd Floor Corridor from the steps of the Sun Parlor on the south, taken during the renovation of the White House. From the temporary steel beams in the foreground, across the steel beams of the 3rd Floor, tie-rods were installed to hold up the 2nd Floor below.

Date(s)

March 7, 1950

Accession Number 71-219

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.