


View of west wall of the Main Stairs



Description

View of west wall of the main stairs from the first floor to the second floor during the renovation of the White House. The wooden support for the original stairs, from first floor to landing below second floor can be seen. Photograph taken from East Room after east wall of stairs was removed.

Date(s)

April 14, 1950

Accession Number 71-267

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.