White House East Basement During Renovation of the White House



Description
Southwest view from the east basement entrance of White House during renovation. The Allis Chalmers Cletrac Diesel-powered shovel is being used to excavate below the basement floor. The earth is carried outside the opening in the south wall and loaded on trucks by a truck crane.

Date(s)
April 28, 1950

Accession Number 71-285

8x10 inches (21x26 cm) Black & White

Related Collection Harry S. Truman Papers

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.