

# Photograph from Rose Room west along north wall during White House renovation



## Description

Photograph from Rose Room (No. 12) west along north wall. The stairway and area above lobby are in the foreground. Note the bow in the large beams above the lobby and corridor. This was taken during the renovation of the White House.

## Date(s)

September 25, 1950

**Accession Number** 71-367

8x10 inches (21x26 cm)      Black & White

**Related Collection** [Harry S. Truman Papers](#)

**Keywords** Building repair and reconstruction      Dwellings      Historic buildings      Presidential residences  
Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.