

View from center hall to southeast corner of the White House during renovation



Description

View from center hall to southeast corner of the White House during renovation. The oval study is at the center. Wire reinforcement and wooden forms are being installed for pouring the concrete floor already completed in the eastern part of the second floor.

Date(s)

November 10, 1950

Accession Number 71-396

8x10 inches (21x26 cm) Black & White

Related Collection [Harry S. Truman Papers](#)

Keywords Building repair and reconstruction Dwellings Historic buildings Presidential residences
Renovation (Architecture)

HST Keywords White House - Miscellaneous - Renovation

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Abbie Rowe National Park Service Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.