


# View from northeast corner of the North Portico of White House during renovation



## Description

View from northeast corner of the North Portico looking east and showing excavation at the northeast corner of the White House. A temporary wooden protection is being erected over the roof at this corner preparatory to raising it, and other corners, to the height of central part.

## Date(s)

July 31, 1950

**Accession Number** 71-351

8x10 inches (21x26 cm)      Black & White

**Related Collection** [Harry S. Truman Papers](#)

**Keywords** Building repair and reconstruction      Dwellings      Historic buildings      Presidential residences  
Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.