

# View of the ceiling of the State Dining Room during White House renovation



## Description

View of the ceiling of the State Dining Room to the west wall. The rough plastering course has been applied to the ceiling with openings left for ornamental frieze, loud speaker grills, and centerpiece. This was taken during the renovation of the White House.

## Date(s)

April 23, 1950

**Accession Number** 71-446

8x10 inches (21x26 cm)      Black & White

**Related Collection** [Harry S. Truman Papers](#)

**Keywords** Building repair and reconstruction      Dwellings      Historic buildings      Presidential residences  
Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.