

# South view in small bedroom Number 18 during White House renovation



## Description

South view in small bedroom Number 18. Plasterer is working on the ornamental frieze. The finish plastering course has been completed on the ceiling, and rough coat on the walls. This was taken during the White House renovation.

## Date(s)

May 3, 1951

**Accession Number** 71-451

8x10 inches (21x26 cm)      Black & White

**Related Collection** [Harry S. Truman Papers](#)

**Keywords** Building repair and reconstruction      Dwellings      Historic buildings      Presidential residences  
Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.