

# Northeast view in Sitting Room during White House renovation



## Description

Northeast view in Sitting Room Number 16 with workman shown sanding the new quartered white oak floor. This was taken during the renovation of the White House.

## Date(s)

February 5, 1952

**Accession Number** 71-630

8x10 inches (21x26 cm)      Black & White

**Related Collection** [Harry S. Truman Papers](#)

**Keywords** Building repair and reconstruction      Dwellings      Historic buildings      Presidential residences  
Renovation (Architecture)

**HST Keywords** White House - Miscellaneous - Renovation

**Rights** Public Domain - This item is in the public domain and can be used freely without further permission.

**Note: If you use this image, rights assessment and attribution are your responsibility.**

**Credit:** Abbie Rowe      National Park Service      Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.