Manchu Iron Works - Anshan, Manchuria



Accession Number 2009-726

Description
Manchu Iron Works in Anshan, Manchuria. Destruction around blast furnace (shown at upper left) caused by demolition, attributed by Chinese Nationalist authorities to Chinese Communist Army. This destruction occurred after the period of Soviet occupancy, during which period skip hoists, blowers and other auxiliaries serving six of the nine blast furnaces at Anshan were removed. Photograph taken during the U.S. Reparations Mission. Edwin Pauley was the U.S. Ambassador on the Allied Reparations Committee from 1945-47 (the committee that assessed the reparations the Axis powers could afford to pay the victors).

Date(s)
June 18, 1946

8x10 inches (21x26 cm) Black & White

Related Collection Pauley, Edwin W. Papers

Keywords Factories Reparations

HST Keywords China - Manchuria

Rights Public Domain - This item is in the public domain and can be used freely without further permission.

Note: If you use this image, rights assessment and attribution are your responsibility.

Credit: Marlin Fenical U.S. Army Signal Corps Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.