Two Story Fire Station in Japan



Description
This two story fire station in Japan was made of concrete and reinforced steel. It is still standing after the bomb, but the windows are blown. The firemen are in uniform and the pumper they have pulled outside is probably now in service. From Basil Rice.

Date(s)
October 1945

Accession Number 2018-211

4x5 inches (10x13 cm) Black & White

Keywords Fire stations War damage

Rights The Library is unaware of any copyright claims to this item; use at your own risk.

Note: If you use this image, rights assessment and attribution are your responsibility.

Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.