Damaged Buildings in Japan after Bombing



Description
These buildings in Japan show that the concrete walls are still standing, but the wood in and around them has been splintered by the blast. The tiles on the roof are buckled and damaged by heat. The windows have been blown out. From Basil Rice.

Date(s)
October 1945

Accession Number 2018-210

4x5 inches (10x13 cm) Black & White

Keywords War damage

Rights The Library is unaware of any copyright claims to this item; use at your own risk.

Note: If you use this image, rights assessment and attribution are your responsibility.

Harry S. Truman Library & Museum.

Attention media: Please make note of this item's accession number. Print out this page and retain it for your permissions records before downloading this image file for possible publication. Library staff cannot sign permissions forms or provide additional paperwork. The Library charges no usage fees for downloaded images.